Cooldown Circuits

10% Current, 63% CFM

spdt

to unit ign (yel)
(use U/D jumper)

from battery

from battery

50% Current, 80% CFM


from AC compressor

spdt

to unit AC (blue)

from battery

Shutdown Circuits



Combination Circuit

Dverride on / off

